

WILFLEX® ARTIST PLUS WHITE #11122WHT

DESCRIPTION

Artist Plus White is an opaque base and highlight white specifically formulated for non-bleed garments. Its fast flash time and superior low after-tack also enables the ink to be used as a flash white. The matte appearance, excellent fiber mat-down and bright appearance ensures Artist Plus is an excellent all round, general-purpose white

PRINTER'S PARAMETERS

1 KII 1 EK 3 I AKAHETEKS		
100 percent cotton,		
non-bleed fabrics ONLY		
None		
60-195 threads/in (24-77		
threads/cm) for optimum		
opacity		
15-20 acceptable, 25-35		
recommended		
Direct, indirect & capillary		
60-90 dual or triple		
durometer squeegees		
Sharp		
45 degrees		
Maximum		
200-210 F (93-99 C)		
320 F (160 C) entire film		
None		
5 percent max (by weight)		
Curable Reducer #10070		
65-90 F (18-32 C). Avoid		
direct sun. Use within one		
year of receipt.		
Wilflex Screen Wash		
Available upon request		

FEATURES

- For use on 100 percent cotton garments
- Fast flashing
- Low after-tack
- Prints through fine meshes
- Use as a first-down, underbase flash white or an overprint stand-alone white.
- Odorless
- Excellent opacity & Optically Bright
- Matte appearance, excellent fiber mat-down

SPECIAL RECOMMENDATIONS

- Due to differences in power, height above ink film and efficiency of the flash drying unit, specific dwell time cannot be given
- To increase production speeds, use finer mesh counts for the flash plate to decrease gel time. Set flash dwell times on heated pallets to simulate production. Adjust your settings so that the ink is just dry to the touch.
- Avoid overflashing, as it can result in poor inter-coat adhesion of overprint colors.
- Use consistent, high tensioned screen mesh to optimize performance properties.
- Perform fusion tests before production. Failure to cure ink properly can result in poor wash fastness, inferior adhesion, unacceptable durability, and increased likelihood of dye migration. Testing procedures for plastisol fusion are outlined in the Wilflex User's Manual.
- Stir plastisols prior to printing.
- Do not dry clean, bleach or iron the printed area.
- Any application not referenced in this product information bulletin should be pre-tested or consultation sought with Wilflex Technical Services Department prior to printing (US - 800-735-4353).

ORDER INFORMATION

FO20004670D2	50 gallon fiber drum, no liner
FO20004670D3	30 gallon fiber drum with liner
FO20004670D8	50 gallon fiber drum with liner
FO20004670ES	30 gallon fiber drum, no liner
FO20004670EV	50 gallon metal drum, no liner
FO20004670EW	50 gallon metal drum with liner
FO20004670L5	5 liter
FO20004670TT	Tote
FO20004670Z1	l gallon
FO20004670Z5	5 gallons

Effective 10/20/03. Not all Wilflex products are available in every country. The information in this publication is based on information and experience believed reliable. Since many factors may affect processing for an application, processors must carry out their own tests and experiments to confirm suitability for intended use. You must make your own determination of suitability for your intended use and environmental acceptability, the safety and health of your employees, and purchasers of your product.

